

Tech & Firmware Notification –

NOS™ - NOS-64 - 16.1.21

Date: September 28, 2020



General NOS™- 64 Release Notes 16.1.21

FEATURE FIXES

- Intel Wifi cannot connect to WPA Enterprise 1/2 (PEAP/MSCHAPv2).
- Boot hangs when VNC password is set (5848q model only).
- Very delayed and sometimes unresponsive behavior when it comes to printing off a test page.
- USB Audio hotplug not fully supported.
- Ctl + Alt + Shift + 0 does not require password as expected.
- DHCP client not registering hostname in DNS for forward & reverse lookup zone.
- 64 bit OS forces primary monitor to be on the left.
- Clean up firmware upgrade script.
- Upgrade script not properly checking the free disk space.
- 6048q Series must enable PXE in BIOS before lanboot can work.
- Log file growing too fast.
- HP Officejet Pro 8600 connected via USB local test page fails regardless of driver selected.
- Clean up reboot after firmware upgrade.
- Shutdown from sidebar takes a long time.
- Enabling PXE not working.
- USB drive mounted twice.
- DNS Client (Resolv.conf) will not initialize correctly under certain conditions, requiring reboot or factory default.
- 6048q Series footstand USB/serial port not functioning.

FEATURE REQUESTS

- Repair boot disk at start-up.
- Added support for Intel Wireless 8265 /8275 Wifi card.
- Added zebra printer selection to the list of drivers. Zebra ZP450.
- Added a "combined output" device which plays on all output devices, fix Disable Onboard Speaker.
- Enabled back-up/restore firmware upgrade.
- Added support for IPv6.
- When we reset the network settings, also reset the cloud manager configuration.
- Terminal active/inactive manager indicator.

Citrix NOS-64 16.1.21 Release Notes

FEATURE FIXES

- Cannot bring up zeroweb GUI until connected to Citrix server.
- Reconnect not working.
- Cannot exclude USB headset from redirection.
- ZeroWeb Browser compatibility with Citrix Cloud.
- Imported certificates not recognized by Citrix Workspace App.

FEATURE REQUESTS

- Upgraded Citrix Workspace App for Linux (2006).
- Added Zoom plugin for Citrix as standard build targets.
- Support for Browser Content Redirection.



VMware NOS-64 16.1.21 Release Notes

FEATURE FIXES

- VMware Workspace One connection does not launch.
- USB headset + webcam + disable onboard speaker use case not working.
- Status icon not correct needed for VMware certification.
- VMware apps display problem (9948v only).

FEATURE REQUESTS

- Changed title of Login to Connect for VMware compliance.
- Added option to disable CRL checking in VMware advanced settings.
- Added Zoom plugin for VMware as standard build targets.
- Updated VMware banners.
- Smart Card removal option to disconnect session.